Approved For Release 2001/09/28 5 ਈඛ-RDP15660446R000100200002-8

FILE INFO

Dor 37414	122	REPRODUCTION F	PROHIBITED	
ACTION	1	6	11	16
,	2	7	12	17
	3	8	13	18
	4	9	14	19
	5	1Ø	15	2Ø

SECRET Ø3Ø548Z OCT 74 CITE

25X1A

PRIORITY


IDEALIST

1. HAVE HAD PROBLEM WITH 1 ANTENNA SYSTEM BEHAVING ERRATIC IN
7 MHZ BAND. REPLACED COUPLER AND 200 FT XMISSION LINE. ALTHOUGH NOT
EQUIPPED TO TEST EITHER COUPLER OR COAX, BELIEVE COUPLER MOST LOGICAN FAULT.

- 2. HAVE SUFFICIENT COAX ON HAND FOR FUTURE MAINTENANCE. WOULD LIKE Q SHIP 1 EA. 490T-2 COUPLER AND 1 EA CABLE ASSY CA102A (COUPLER CONTROL CABLE). THE COUPLER CONTROL CABLE WOULD ENABLE GROUND TESTING FUTURE COUPLER FAULTS AND BE AVAILABLE AS REPLACEMENT FOR WEATHER DE-25X1A TERIOATION OF IN PLACE CABLES.
- 3. IF ITEMS AVAILABLE HOPE CAN BE CARRIED TRIP TO IN LIGHT OF EXPERIENCE WITH PAST HAND CARRY ITEMS, WOULD BE HELPFUL

 IF END ASSIST THRU CUSTOMS ETC. E2 IMPDET

BT BT



Approved For Release 2001/07/28: CIA-RDP75B00446R000100200002-8